


R=5111.20
L=714.48
T=357.64
CL=714.02
CB=5 60°21'28" E

Found Concrete Monument

Larry M. Wingo, et ux
Called 50 Ac.
1056/348 D.R.G.C.



⑦
18.876 Ac.
Block I

⑥
16.553 Ac.

⑤
12.990 Ac.

④
15.980 Ac.

③
10.494 Ac.

Flood Hazard Area
Zone A

②③
20.921 Ac.
Block I

②④
15.971 Ac.

②⑤
15.391 Ac.

②⑥
14.338 Ac.

Block I

②⑦
10.881 Ac.

Set 5/8" Iron
Pin Fence Line
Angle

Fence Corner
Set in Concrete

Pond


②⑩
10.100 Ac.
Block I

②⑨
14.683 Ac.

②⑧
16.193 Ac.

②⑦
11.244 Ac.

Fence Corner
Set in Concrete



Farm-To-Market Rd 362

Vista Hills Dr

Google earth

© 2015 Google

Imagery Date: 10/3/2014 30°20'38.48" N 95°59'11.79" W elev 249 ft eye alt 8365 ft

1995



AxC

PaD

LtD

FrC

W

LtD

Farm-To-Market Rd 362

BrD

LtD3

LtD3

FrC

FrC

BrD

Vista Hills Dr

LtD


KID

© 2015 Google

Google earth

1995

Imagery Date: 10/3/2014 30°20'38.48" N 95°59'11.79" W elev 249 ft eye alt 8365 ft



Farm-To-Market Rd 362

BM 301

Vista Hills Dr 300

© 2015 Google

Vista Hills Dr

Google earth